

Dante Accelerator Firmware V1.0.1 Release Notes

Main Revisions and Enhancements

V1.0.0 to V1.0.1

Specification Changes

- Disabled the Pull up/Pull down settings in OS X 10.8 which do not support Pull up/Pull down.
- This firmware does not support Dante Accelerator Driver V1.0.0 for Mac. V1.0.1 or later is required for use

Fixed Bug

- Solved the problem in which the noise might occur when changing the Pull up/Pull down settings in Mac OS X 10.6 or 10.7.

Known Issue

- The Dante Accelerator for which Pull up/Pull down is set to enable does not work properly in OS X 10.8. Before installing, set the Pull up/Pull down setting to "None"

Company and product names that appear in this document are the trademarks or registered trademarks of their respective companies.

(C) 2013 Yamaha Corporation All Rights Reserved.

Dante Accelerator Firmware V1.0.1 リリースノート

主なアップデートの内容

V1.0.0 → V1.0.1

仕様変更

- OS X 10.8 では Pull up/Pull down をサポートしていないため、設定を無効にしました。
- Dante Accelerator Driver for Mac V1.0.0 と互換性がありません。Dante Accelerator Driver for Mac を V1.0.1 以降にアップデートしてお使いください。

修正した不具合

- Mac OS X 10.6 または 10.7 で使用するとき、Pull up/Pull down の設定を変更したあと、ノイズが発生する場合がある問題を修正しました。

既知の不具合

- Pull up/Pull down の設定をされた Dante Accelerator を OS X 10.8 の Mac にインストールすると、正常に動作しません。事前に Pull 設定を「None」に設定してからインストールしてください。

本文に掲載されている会社名および商品名等は、各社の登録商標または商標です。

(C) 2013 Yamaha Corporation All Rights Reserved.